



| DATE | TOTAL TIME IN SERVICE | TOTAL TIME SINCE OVERHAUL | TACH OR RECORDING METER TIME | DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|--------|-----------------------|---------------------------|------------------------------|---|
| | N/A | N/A | N/A | TOTALS brought forward from previous page |
| 4-3-07 | 0 | 0 | 0 |  <p>This propeller S/N 061489 installed on LC42-550FG S/N 42563 at time of aircraft manufacture.</p> <p><i>Annie Mills</i> Columbia Aircraft Mfg.</p> |
| | | | | |
| | | | | |
| | | | | |
| 5-8-07 | 0 | 0 | 0 |  <p>This propeller has been dynamically balanced per the Microvibe user's manual and McCauley Memo COL-06-145SKG.</p> <p><i>Annie Mills</i> Columbia Aircraft Mfg.</p> |
| | | | | |
| | | | | |
| | | | | |

| | | |
|---|---|---|
| 0 | 0 | 0 |
| 0 | 0 | 0 |

SUB-TOTALS this page

TOTALS-Carry forward to next page

| DATE | TOTAL TIME IN SERVICE | TOTAL TIME SINCE OVERHAUL | TACH OR RECORDING METER TIME | DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|------|-----------------------|---------------------------|------------------------------|---|
| | ○ | ○ | ○ | TOTALS brought forward from previous page |


Prop Model :
 Prop Serial # : 061489
 Prop TSN/TSO : 145.4
 Prop Position : N/A
 Log Book : Propeller

A/C Reg # : N/A
 Work Order # : SRSE32681
 A/C Ser # : 42563
 A/C Time : 145.4 Hobbs
 Date : 7/8/2008



ATLANTIC AERO
 Serving the World through Aviation
 P.O. Box 35408 Greensboro, NC 27425
 Tel 800-334-2001 Fax 336-668-4434
<http://www.atlantic-aero.com>

*I certify this PROPELLER has been inspected in accordance with a 100 HOUR inspection and is approved for return to service.

Signed:  for Atlantic Aero, Inc. CRS# EWGR752D


AERO INDUSTRIES, INC
 5745 HUNTSMAN RD.
 RICHMOND INTL AIRPORT
 VA. . 23250-2411


DATE - 8 JUNE 2009
 MAKE - MCCAULEY
 M/N - D3A34C444-F
 S/N - 061489
 REG. # N1170B
 HOBBS: 167.8


ENTER IN : PROPELLER RECORD

COMPLIED WITH THE FOLLOWING IN ACCORDANCE WITH CESSNA COLUMBIA 350 AMM UNLESS OTHERWISE NOTED: PRELIMINARY INSPECTION ACCOMPLISHED PER AERO INDUSTRIES, INC. FORM 005. COMPLIED WITH ANNUAL INSPECTION IN ACCORDANCE WITH CESSNA 350 AMM CHAPTER 5-20-00 INSPECTION CHECKLIST DATED 2/15/2008. REPLACED ALL THREE PROPELLER DE-ICE BOOTS DUE TO TEARS. INSTALLED NEW P/N'S B40245-60 BOOTS AND NEW SMR6201 STRAPS PER MCCAULEY SERVICE INSTRUCTIONS. OPERATIONAL CHECK GOOD ON PROPELLER DEICE SYSTEM. TOUCHED UP PAINT ON PROPELLERS AS REQUIRED. COMPLIED WITH ALL LEAK AND OPERATIONAL CHECKS REQUIRED FOR ANNUAL INSPECTION AND REPAIRS DURING GROUND ENGINE RUN. ALL LEAK AND OPERATIONAL CHECKED GOOD. ALL AD'S ARE CURRENT TO DATE AND COMPLIANCE RECORDS UPDATED AS REQUIRED. COMPLIED WITH FINAL INSPECTION FOR WORK ACCOMPLISHED UNDER THIS WORK ORDER. PROPELLER TOTAL TIME:: 167.8 HOURS

THE MAINTENANCE DESCRIBED ABOVE WAS INSPECTED AND REPAIRED IN ACCORDANCE WITH CURRENT TECHNICAL DATA AND FAA REGULATIONS AND WITH RESPECT TO THE WORK PERFORMED, THE AIRCRAFT IS APPROVED FOR RETURN TO SERVICE. DETAILS OF THIS INSPECTION AND/OR REPAIR ARE ON FILE AT THIS REPAIR FACILITY UNDER WORK ORDER NO. 51601.

SIGNATURE:  CRS Certificate No: BIER466C
 CHIEF INSPECTOR

PROP MCCAULEY D3A34C444-F SER.# 061489 A/C N1170B
 DATE 10/22/2013 TOTAL TIME 380.8
 I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN 100 HOUR INSPECTION AND HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION.
 A&P 2163416
 DONALD MCDANIEL 

PROP MCCAULEY D3A34C444-F SER.# 061489 A/C N1170B
 DATE 11/10/2014 TOTAL TIME 0423.5
 I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN 100 HOUR INSPECTION AND HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION.
 A&P 2163416
 DONALD MCDANIEL 

| | | | |
|--|--|--|-----------------------------------|
| | | | SUB-TOTALS this page |
| | | | TOTALS-Carry forward to next page |